

The heart rate is not detected.

There could be a few reasons that the CODA detects elevated blood pressures. The most common causes are related to a low tail blood volume (indicated by a tail temperature that is too low), cuffs that are too large or placed too loosely on the tail, or related to the physiological effects of anesthetic agents.

Please send us a sample of your data in Simple Report form, a few screenshots of the graphs from that session and a photo of your set up with the cuffs on the animals' tails. We will be happy to review it with you.